

# MEGA LIFT CHERRY

## INDUSTRIAL SOLVENT FOR DEGREASING LIFT STATIONS

LONG LASTING DEODORIZER  
MUNICIPAL & INDUSTRIAL DEGREASER  
ASPHALT RELEASE AGENT

### NET CONTENTS (in U.S.GALLONS):

<input type="checkbox"/> 5	<input type="checkbox"/> 15
<input type="checkbox"/> 20	<input type="checkbox"/> 30
<input type="checkbox"/> 35	<input type="checkbox"/> 55

Manufactured Exclusively For:



P.O. Box 204, Hawleyville, CT  
203.628.0154  
ampchemical.com

This specialized formulation is a floating solvent system possessing degreasing and deodorizing properties. This product will clean vertical surfaces on lift station, wet wells, and similar treatment facilities. Added directly to wet wells it effortlessly cleans and degreases as the water level fluctuates. It also "seals" offensive odors, containing these odors emitted from lift stations. **THIS PRODUCT ALSO MAKES AN EXCELLENT GENERAL PURPOSE DEGREASER AND ASPHALT RELEASE AGENT.**

### USE TO:

Remove accumulated sewage, grease, oils, fats, calcium soaps, fatty acids, and magnesium soaps that have formed deposits on walls. This product will help return station to optimum efficiency by removing or substantially reducing this debris which can reduce volume capacity of wet wells and emit offensive odors.

### DIRECTIONS

**LIFT STATIONS:** Pour directly into manhole or station pit. Use approximately 32 oz. (1 quart) for each square foot of water surface, or until a layer of 2-4 inches of **MEGA LIFT CHERRY** is floating on the water's surface. This special non-emulsifiable formula stays on the surface for continuous action.

**GENERAL DEGREASING:** Apply by spraying, dipping, wiping, brushing or soaking.  
**ASPHALT RELEASE AGENT & REMOVER:** Pre-spray truck beds and equipment for easiest release. Post spray asphalt accumulated on equipment to soften for easier removal.



**WARNING**  
Combustible Liquid  
Causes Skin Irritation  
May Cause an Allergic Skin Reaction



Keep away from open flames. No Smoking. Avoid breathing vapors, spray or mist. Wash hands thoroughly after handling. Contaminated work clothing must not be allowed out of the workplace. Wear eye protection, face protection. If on skin: Wash with plenty of soap, water. If skin irritation or rash occurs, get medical attention. Take off contaminated clothing and wash it before reuse. In case of Fire: Use ABC-powder to extinguish. Store in a well-ventilated place. Keep cool. Dispose of contents to an approved waste disposal plant.

### FIRST AID

Never give anything by mouth to an unconscious person. If you feel unwell, seek medical advice (show the label where possible). **If On Skin:** Immediately remove all contaminated clothing. Rinse skin with water/shower. Wash with plenty of soap and water. Wash contaminated clothing before reuse. If skin irritation occurs, get medical attention. **If Swallowed:** Rinse mouth. Do NOT induce vomiting. **If Inhaled:** Remove person to fresh air and keep comfortable for breathing. **If in Eyes:** Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.

### Precautions for Safe Handling

No open flames. No smoking. Take precautionary measures against static discharge. Avoid breathing vapours, spray, mist.

**Keep Away from Children**  
**For Emergencies, call CHEMTREC: 800-424-9300**